

Assessment Impact by Course Objectives
Palau Community College
Program (CT) - Construction Technology

Program (CT) - Construction Technology

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 1

Interpret roof framing plan and exterior detail.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Demonstrate understanding of a roof framing plan and exterior detail. Signature assignment: Midterm Exam	70% of the students assessed will perform at the proficiency level.		Yes
Complete assigned project to demonstrate roof framing plan and exterior detail skills. Signature assignment: Project	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Midterm Exam - 06/02/2015 - 88% of the students assessed performed at the proficiency level Expected Student Performance Met: Yes Related Documents: ct123Evidence.pdf	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only 1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem. This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.		2014 - 2015 (Spring 2015)
Midterm Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Related Documents: CT CLO1-5 fe.pdf			
Midterm Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT123 projects.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 2

Select and installs roof frames.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Explain and/or demonstrate the installation of roof frames. Signature assignment: Midterm Exam	70% of the students assessed will perform at the proficiency level.		Yes
Compete assigned project to demonstrate skills of selecting and installing roof frames. Signature assignment: Project	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Midterm Exam - 06/02/2015 - 88% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: ct123Evidence.pdf	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only 1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem. This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.		2014 - 2015 (Spring 2015)

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Project - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT123 projects.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)
Midterm Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT CLO1-5 fe.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 3

Select and install roofing materials.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Explain and/or demonstrate the installation of roofing materials. Signature assignment: Midterm Exam	70% of the students assessed will perform at the proficiency level.		Yes
Complete assigned project to demonstrate skills in selecting and installing roofing materials. Signature assignment: Project	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Midterm Exam - 06/02/2015 - 88% of the student assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: ct123Evidence.pdf	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only 1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem.		2014 - 2015 (Spring 2015)

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
	This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.		
Project - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT123 projects.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)
Midterm Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT CLO1-5 fe.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 4

Select and install exterior wall sidings and cornice coverings.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Explain and/or demonstrate the installation of exterior wall sidings and cornice coverings. Signature assignment: Final Exam			Yes
Complete assigned project to demonstrate skills in selecting and installing wall sidings and cornice coverings. Signature assignment: Project	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Final Exam - 06/02/2015 - 88% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: ct123Evidence.pdf	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only		2014 - 2015 (Spring 2015)

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
	1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem. This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.		
Project - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT123 projects.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)
Final Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT CLO1-5 fe.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 5

Select and install exterior door and windows.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Explain and/or demonstrate the installation of exterior doors and windows. Signature assignment: Final Exam	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Final Exam - 06/02/2015 - 88% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents:	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only		2014 - 2015 (Spring 2015)

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
ct123Evidence.pdf	1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem. This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.		
Final Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: CT CLO1-5 fe.pdf	07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.		2013 - 2014 (Spring 2014)

CLO: CT 123 - Roof Framing & Exterior Finishing: CLO 6

Apply exterior finishing.

CLO Assessment Cycle: 2014-2015 (Spring 2015)

CLO Status: Active

Means of Assessment			
Means of Assessment	Expected Student Performance	Notes	Active
Explain and/or demonstrate the application of exterior finishing. Signature assignment: Final Exam	70% of the students assessed will perform at the proficiency level.		Yes

Results			
Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
Final Exam - 06/02/2015 - 88% of the students assessed performed at the proficiency level. Expected Student Performance Met: Yes Related Documents: ct123Evidence.pdf	06/02/2015 - No significant change from last semester however absenteeism continue to have greater effect on the results. 7 out of 8 students enrolled were assessed and only 1 student performed below the proficiency level due to excessive absences several attempts were conducted thru Student Service Office but absences persisted. Perhaps dormitory residence assistance must be increased as many students residing in the dorm continue to have absenteeism problem.		2014 - 2015 (Spring 2015)

Results

Summary of Data Collected	Use of Results	Follow-Up	Semester Assessed
<p>Final Exam - 07/07/2014 - 100% of the students assessed performed at the proficiency level.</p> <p>Expected Student Performance Met: Yes</p> <p>Related Documents: CT CLO1-5 fe.pdf</p>	<p>This semester the signature assignment was tailored to accommodate the students limited hands on opportunities on actual projects. We'll continue to seek more opportunities next school year.</p> <p>07/07/2014 - No revision needed to the course at this time as the expected student performance was met. However, attendance is a problem for only 2 students completed the course.</p>		<p>2013 - 2014 (Spring 2014)</p>